STANDARD INSTRUMENT DEPARTURE CHART (SID) - ICAO

TRANSITION LEVEL by ATC
TRANSITION ALTITUDE 7000

ZURICH LSZH
TEMPO SID RWY 14 - RNAV (DME/DME or GNSS)

ACTIVATION BY NOTAM OR BY AIRPORT AUTHORITY ONLY



COR: SID validity indicators, OBST, VAR

COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
- Cross DEGES / GERSA / VEBIT climbing to/at last received and acknowledged FL but not below MCA*.
- Continue climb to FPL FL.

*Leave last received and acknowledged FL or ALT earliest three minutes after airborne.

THIS PAGE INTENTIONALLY LEFT BLANK