
AERODROME GROUND MOVEMENT AND AIRCRAFT PARKING CHART - ICAO TOWER 118,1 TAXIING 121.7 IRKUTSK, RUSSIA





Surface: Stands: 1-8 - Asphalt 1-4 5-8 Strength: Stands: - PCN 20/R/C/X/T - PCN 28/R/C/X/T TAXIWAYS: 1(MAIN), 2, 5, 6, 7, 8, 11 - 21m Width:

- 34m - 14m 10, 10A - 17m 12, 14 - 12m 13. 13A - 10m

Surface: 1-14 - Asphalt-Concrete

Strength: 1(MAIN), 2 - PCN 31/R/B/X/T (index 6) PCN 24/F/D/X/T (index 4)
PCN 44/F/D/X/T (index 6)
PCN 45/R/C/X/T (index 6)
PCN 56/R/C/X/T (index 6) 7(Concrete from stand 65 to stand 69)

- PCN 34/R/C/X/T (index 6) - PCN 47/R/B/X/T (index 6) - PCN 34/R/C/X/T 8. 11 - PCN 14/R/C/X/T (index 3) 10 - PCN 35/R/B/X/T (index 6) 10A - PCN 34/R/C/X/T

- PCN 18/R/B/X/T (index 3) - PCN 27/F/D/X/T

- PCN 18/R/B/X/T

WARNING: 1. Parts of RWY in front of RWY displaced thresholds are AVBL for taxiing of ACFT after landing.

2. Taxiing of: index 6 ACFT (An-124, II-76, II-62, A-310, B767 ACFT) along TWY 1, 2, 5, 6, 11; index 6 ACFT, except An-124 ACFT, along TWY 7, 8 (to stand 22);

index 4 ACFT (Tu-134, Yak-42 ACFT) along TWY 8 (from stand 15 to stand 9);

index 4 ACFT (An-12, II-18 ACFT) along TWY 4, 10; index 3 ACFT (An-24, An-26 ACFT) along TWY 9, 12, 14 shall be carried out at reduced speed, strictly along the taxi guide line.

3. TWY 10A is AVBL only for taxiing of military ACFT.

4. Taxiing of An-124, II-18, An-12 ACFT shall be carried out under inner engines power.

5. TWY edge lights are installed on all TWY.

6. Taxiing into stands 26-39 shall be carried out by marshaller's instruction, via the adjacent stand. (See box **①**).

7. While parking onto stands 9-15, taxiing along TWY 8 shall be carried out to abeam stand 22, then, under control of the aerodrome engineering service, taxiing from stand 15 to stand 9 is allowed for ACFT with a wingspan of not more than 35m, strictly after the "FOLLOW ME" vehicle. (See box 2). ACFT with a wingspan of more than 35m shall taxi into stands 9-15, when the stands to the right of the taxi route are vacant, or by towing

8. When stand 22 is occupied, taxiing along TWY 8 on segment from TWY 7A to stand 15 is prohibited. Taxiing to the apron and stands 9-15 shall be carried out along TWY 7A.

9. In exceptional cases, for arrival of II-96 type ACFT, marking of taxi route and ACFT parking position shall be painted by yellow dotted line.

10. Taxiing of index 4, 5, 6 ACFT in the night-time and in the day-time when visibility is 400m or less shall be carried out only after the "FOLLOW ME" vehicle. Taxiing of ACFT along TWY 1 shall be carried out without a "FOLLOW ME" vehicle in the dayand night-time under any meteorological conditions.

STANDS:

Surface: Stands 65-69 - concrete, other stands - asphalt.

- PCN 20/R/C/X/T - PCN 28/R/C/X/T Strength: 1-4 (Apron) 5-8 (Apron) 9-15, 22 (Short-distance stands) - PCN 13/R/C/X/T 16-21 (Middle-distance stands) - PCN 24/R/C/X/T 26-51 (Stands for piston-engined ACFT) - PCN 24/R/B/X/T - PCN 41/R/B/X/T 56-62, 64 (Cargo apron (remote stands)) 65-69 (Middle-distance stands) 70 (Cargo apron (remote stands)) - PCN 64/R/C/X/T - PCN 44/F/D/X/T

STANDS: ACFT types:

26-51 - An-24, An-26, Yak-40 (index 3*) - Tu-134, An-12 (index 4*) - B737, A-319, A-320 (index 4*) 1-21, 59-61 1-21 1-21 - Tu-154 (index 5*) 2, 4, 6, 8 - Tu-204, Tu-214 (index 5*) - B757 (index 5*) 4, 6, 8 1-22, 58-69 - A-321, B737-400, B-737-800, BD-700 GLOBAL EXPRESS,

BAC-111, FOKKER-100 and their modifications 65-67, 69 - B737-900 and its modifications

64-69 - II-76, II-62 (index 6*) 22, 65-69 - A-310, B767 (index 6*) - II-96 (index 6*), II-96-400 and its modifications

62 - An-124 (index 6*) - ACFT with ACN more than TWY PCN facing RWY

*Parking of other ACFT types with the same index or less is permitted.

- 1. The decision on ACFT parking/docking shall be taken by controller
- 2. Parking of II-62 ACFT on stand 6 is allowed from October 15 till April 15.
- 3. Stands 2, 4, 6 are allowed for parking of Tu-204, Tu-214 ACFT with displacement by 2m to the north and when stands 1, 3, 5 are vacant
- 4. Parking of Il-76 ACFT is allowed:
- on stands 17-19, 21 when adjacent stands are vacant; - on TWY 8 from TWY 11 to TWY 6.
- 5. Apron (stands 1-8) has a slope from 0.026 to 0.037.
- 6. Stands 26, 40, 41 have a slope from 0.023 to 0.025.

STAND NR	LATITUDE	LONGITUDE	DIRECTION (TRUE)
1	N52 16.3	E104 21.1	267°57.1'
2	N52 16.3	E104 21.1	087°15.9'
3	N52 16.3	E104 21.2	267°56.9'
4	N52 16.3	E104 21.2	087°42.7'
5	N52 16.3	E104 21.3	267°08.1'
6	N52 16.3	E104 21.3	088°10.3'
7	N52 16.3	E104 21.4	268°25.4'
8	N52 16.3	E104 21.4	088°38.4'

13, 13A

12